



# State of Utah

### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

epresentatives Present During the Inspection:		
Company	Jaren Jorgensen	
OGM	Karl Houskeeper	
OGM	Daron Haddock	

# **Inspection Report**

Permit Number:	C0150025
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, November 14, 2012
Start Date/Time:	11/14/2012 8:30:00 AM
End Date/Time:	11/14/2012 1:00:00 PM
Last Inspection:	Tuesday, October 23, 2012

Inspector: Karl Houskeeper,

Weather: Clear Skies, Temp. 23 Deg. F.

InspectionID Report Number: 3293

Accepted by: jhelfric

11/29/2012

Permitee: CASTLE VALLEY MINING LLC Operator: CASTLE VALLEY MINING LLC

Site: BEAR CANYON MINE

Address: 2352 NORTH 7TH STREET, UNIT B, GRAND JUNCTION CO 81501

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

10,991.83	Total Permitted		
40.46	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Minera	al C	)wn	ers	hip
<b>~</b>	Fe	dera	ı	

Types of Operations

✓ Underground

State Surface

County Loadout

✓ Fee Processing

Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

-Karl R. Nouskeeper

Inspector's Signature:

Karl Houskeeper,

Inspector ID Number: 49



Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Wednesday, November 14, 2012

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.

   For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
   Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		~	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<b>✓</b>		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>V</b>		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	<b>~</b>		✓	
6.	Disposal of Excess Spoil, Fills, Benches	<b>✓</b>	<b>✓</b>		
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>✓</b>	<b>V</b>		
8.	Noncoal Waste	<b>✓</b>		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Wednesday, November 14, 2012

Page 3 of 3

# 2. Signs and Markers

The mine identification sign is in place at the entrance into the mine permit area. The sign contains the name, address, phone number and permit number in accordance with the Utah R645 Coal Rules.

#### 4.a Hydrologic Balance: Diversions

Diversions are functional throughout the mine site.

# 4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment ponds were found to be functional and below the 60% clean elevation. Material in Pond be has been pulled into a pile in the interior of the pond in an effort to let the material dry before removal.

## 5. Explosives

Powder and cap magazines were observed. They are signed and grounded properly.

#### 8. Noncoal Waste

A few items of noncoal waste was observed throughout the mine site. A more heavy concentration of items were observed around the base of the noncoal waste storage dumpster.